



DRAWING KEY	
	Extent of drip line of existing tree, location from survey by BCLS Land Surveyor
	Extent of drip line of existing tree, approximate location from onsite observation by DK
	Tree recommended for Removal (marked are by-law sized, non by-law sized and dead trees, refer to summary of tree removal in paragraph 5.0 in attached arborist report for exact number of by-law sized trees recommended for removal)
	Dead Tree or Stump
	Tree Number of by-law sized tree (DBH 20cm and larger) referred to in existing trees list and report
	Tree Number of non by-law sized tree (DBH smaller than 20cm) referred to in existing trees list and report
	Location of tree protection barrier to be installed before start of other work on site. Note: City of Vancouver requires protective barrier be installed as a pre-condition for Building Permit.
	Proposed Building Footprint
	Proposed Underground Parking Footprint

Observations and recommendations by Florian Fisch, ISA Certified Arborist PN-7921A.
 Observations made January 19, 2016.
 This drawing is to be read in conjunction with Existing Trees Report for this site by Durante Kreuk Ltd, dated October 02, 2017

Refer to sheet T-02 for existing Trees Inventory

existing trees retention and removal plan Hull Street + East 20th